Sharity Road (House) (Marlboro Plank House)
North side of Sharity Road, .5 mile east of
State Route 841 (Greenlawn-Springdell Road)
Green Lawn Vicinity (West Marlborough Township)
Chester County
Pennsylvania

HABS, PA, 15-GRELAN

PHOTOGRAPHS

HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
Heritage Conservation and Recreation Service
Department of the Interior
Washington, D.C. 20243

United States Department of the Interior Heritage Conservation and Recreation Service Washington, D.C. 20243

COMPILER, AFFILIATION

Deboran S. Burns, Historic American

DATE

1979

HAGS, FA, IS-GRELA, V, 1NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY

ARCHITECTURAL DATA FORM

STATE	COUNTY	JOWN OR VICANITY
Pennsylvania	Chester	Green Lawn Vicinity (West Marlborough Township)
HISTORIC NAME OF STRUCTURE		HABS NO.
Sharity Road (House)	(aassa seenaa 1011-11111a)	PA-160
SECONDARY OR COMMON NAMES C	DE STRUCTURE	
Marlboro Plank House	, sings, since	
	LOCATION FOR RURAL SITES)	21 - 4 -
North side of Sharity Ros Road).	ad, 5 mile east of State Ro	ute 841 (Greenlawn-Springdell
DATE OF CONSTRUCTION (INCLL	IDE SOURCE) (ARCHITECT(S) (INCLUDE SOURCE)
Probably built early 18th		
	. AND HISTORICAL, INCLUDE OR	IGINAL USE OF STRUCTURE)
		vival of a small early eighteenth
century house.	ordinator sales and a remorphism	
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (1	NCLUDE STRUCTURAL SYSTEMS)	
Sawn horizontal boards w	ith chinking (little chinkin	g remains) and vertical corner post
covered with horizontal SHAPE AND DIMENSIONS OF STR	wooden siding RUCTURE (SKETCHED FLOOR PLAN	IS ON SEPARATE PAGES ARE ACCEPTABLE
		e exposing random rubble basement
on the south (front) ele- EXTERIOR FEATURES OF NOTE	vation.	
		ons of the horizontal siding have
been removed; exterior ra	andom rubble chimney on east	side.
LUTGOLOR SEATURES OF WOTE	(DECCRIPE C) 000 DIAMS 12 NO	T CHETCHED
INTERIOR FEATURES OF NOTE ((DESCRIBE FLOOR PLANS, IF NO	II SKEICHED)
MAJOR ALTERATIONS AND ADDIT		
Small one-story frame add early twentieth century.	lition on east elevation; no	velty siding added on east elevation
PRESENT CONDITION AND USE Poor condition as of 1960		
OTHER INFORMATION AS APPROP	PRIATE	
	\lnot,	
COURCES OF INFORMATION (1910	THAT (307) DA ON ONTO AND A	OLOTED STATE DESIGNATION SET
SOURCES OF INFORMATION (INC	LOUE LISTING UN NATIUNAL RE	GISTER, STATE REGISTERS, ETC.)